

# User Interface SolidWorks


Last Modified on 08/01/2025 9:25 am CET

## S-button



Commonly used - Commands appear. There are different commands depending on sketch, part, assembly or drawing-mode.

### S-button in Sketch




### S-button in Part



---

## Mouse Gesture


- **Customizable in 4 modes Sketch, Part, Assembly and Drawing**
- **Hold down RMB move mouse to desired gesture**



If you run out of commands bring the "S" to the ring. Perfect for users with space mouse.


## R-button

Use R keyboard button for quick access to recently opened documents.



## Open Documents


- Toggle thru open files Ctrl + Tab; 2 ways
  - Hold down Ctrl key as you sequence thru all open files w. tab
  - Hold down Ctrl key and hit tab > Release both keys. SW switches to latest open file.



## Graphics Area


Hold down Right mouse click to reach commonly used commands. There are different commands depending on sketch/part/asm/drw-mode.

Upper section (Graphics Area) can be customized beside the default setup.



## Quick Hide

Hold the cursor over a part + "Tab" button on the keyboard. Press "Shift+Tab" to show hidden parts. This works for both ingoing parts in an assembly and bodies in a multi-body part.



Press "G" to magnify the area surrounding the cursor.

